

BUILDING SCIENCE LIVE
JUNE 17, 2021

Failing Forward: Learning from Forensic Investigations

Brian Hubbs, P.Eng.
John Straube, PhD, P.Eng.

RDH



1

RDH BUILDING SCIENCE

© RDH Building Science, Inc. 2021

All rights reserved. No part of this presentation may be reproduced or transmitted in any form by any means, electronic, mechanical, photocopy, recording, or other without prior written permission.

For permissions to use this content, email onlinelearning@rdh.com.

RDH

Disclaimer

This material is intended to be used for reference, continuing education, and training purposes only. Neither RDH Building Science, Inc., nor the persons presenting the material, make any representation or warranty of any kind, express or implied, with regard to whether the material is appropriate for, or applies to, any specific project, circumstance or condition. Applicable and current laws, codes, regulations, standards and policies, as well as project and site-specific conditions, procedures and circumstances must always be considered when applying the information, details, techniques, practices and procedures described in this material.

2

What are Forensic Investigations?

→ “the application of professional engineering principles and methodologies to investigating failures and incidents, usually to determine causation”. From: *Forensic Engineering Investigations*, PEO 2016.

→ Why?

- Stop damage
- Inform repair design
- Assess responsibility






3

Process & Approach

- Failures and buildings are highly individual
- However, standard investigation and analysis processes should be considered in developing your plan
- Some good advice available

4

Forensic Standards



5

First Step... Collect Data

- Go to site, get photos, ask people
 - Beware others' conclusions, witnesses are unreliable
- Observations
 - Extent, patterns
 - *Your senses, experience, and building science knowledge are the most important tools*
- Diary of project, dates of problems
- Design documents, materials, systems, contractor, trade, designer, owner
 - Contract drawings, shop drawing etc. often have changes!

6

Assessment / Interpretation

→ Experience

- Have we seen similar failures before?
- What factors are the same?
- What factors are different?
- Be open to new failure modes!

7

Assessment / Interpretation

→ Science, basic principles

- Allows for reliable relative comparisons
 - E.g. Air leakage vs. diffusion
- Can often *rule out* causes / mechanisms
 - E.g. HVAC vs. capillary pressures and rain leaks

→ Calculations and simulations

- Always approximate, sometimes useful
- Often done poorly

8

Assessment / Interpretation

→ **Develop hypotheses to explain observations**

- Compare evidence to hypothesis being tested
 - Some evidence is more reliable than others
 - Extraordinary claims require extraordinary evidence

→ **Provide some estimate of confidence of your conclusions**

- ... and what might be done to improve it

9

Case study

10

Case Study: High-Rise Condensation


- Simplified in this presentation, focus on one part of building
- Federal Courthouse
- Upstate New York (cold)
- Precast concrete



11

Problems


- Construction underway
- “Water is cascading down our elevator shaft!”



12

Problems

- Construction underway
- Late January problem:
 - water running down wall, onto floor, under raised access floor into elevator shaft



13

Field Investigation


- High indoor humidity
- Long cold snap, followed by warming
- Good air barrier
- ... but convection



14

Convection Loop

- Air gap intentionally provided in design!
- Imperfect air seal at upper and lower levels allowed




Cold air falls

so...

in cold weather:

- **Cavity air pushes into building at bottom**
- **Drags warm indoor air into cavity at top**


Experience has shown this to be a common problem




15

Design Drawings - Ellipse Wall

A vapor barrier is not an air barrier
...and vice versa




16




17




18



19



20




21




22



23




24



25

Laboratory testing


- Lab tests can be used to:
 - Prove/disprove theories
 - Confirm material assumptions
 - Feed computer models
- In this case, simple tests
 - Material, not system tests
 - Water uptake test (cores)
 - Vapor permeance test



26


Computer modeling

- “All models are wrong, some are useful”
- Goals
 - Explain / replicate observed performance
 - Model repair strategies
 - Explore risk factors
- WUFI 1D used in case study




27


Detailed View of Wall Model




28




29



30




31



32

Summary of Simulations



33

Modeling results

- **Model can predict problem observed**
 - Building science calculations & simple lab testing needed of course
- **Perfect airseal is not needed for repair**
 - Define performance requirements and inspection protocols
- **Manage cold weather humidity inside**
 - Requires HVAC and operational integration

34

Solutions

- After forensic investigations we usually need to fix the building!

35

Appropriate solutions

- Options: Do Nothing, Repair, Replace, Modify operation, etc.
- Good, better, best
 - Advise the client of pros and cons
- Can't always do the best repair
 - Always present ideal/best as an option for comparison
 - Cost, schedule, disruption, etc. normally involve
 - Consider consequence of doing nothing?

36



37



38

Forensic Conclusions

- General procedures and approaches are available
 - Almost every project requires modification
- Senses, experience, and building science knowledge are the most important tools
 - Fancy widgets are sometimes nice, never sufficient
- Blend site observations, calculations, lab work, modeling to develop sensible reliable solutions
 - Different projects demand different solutions


39



Break for Questions

RDH

40



41

Condensation Issues

- Condensation at window interior surfaces experienced since building was new
- Condensation at interior surface of windows, inside the insulating glass units (IGUs)
- Mold growth at the walls and ceiling surfaces near the windows

RDH

42

Previous Work by Others

- Severe condensation issues noted in Five Year Performance Review
- Extent and severity of issues documented in forensic investigation reports by 2 other consultants
- Window system, installation configuration, and interior conditions noted as cause.
- RDH retained to provide a 2nd opinion




43

Previous Work by Others

- Previous two consultants:
 - Missing thermal breaks at window frames
 - Air leakage around window frames
 - Failed perimeter seal of insulating glass units (IGUs), leading to condensation between the window panes (1)
 - Problematic window installation detail - window frame offset from the plane of the wall insulation
 - Several suites found with higher relative humidity levels, though suites with normal RH found to have some condensation
 - Fungal growth at interior wall/ceiling surfaces
 - No testing or review of HVAC system



44



45

Previous Work by Others

→ Consultant 1 recommendations:

- Strategy 1 - Occupant lifestyle change/review ventilation
- Strategy 2 - Retrofit existing operable windows due to (perceived) lack of thermal break \$275K
- Strategy 3 - Replace IGUs with warm edge technology (WET) \$4.5M
- Strategy 4 - Replace all windows \$6.7M

5. CLOSURE


Strategy 1 should be implemented regardless, at least as far as educating occupants about what steps they can take to avoid compounding the incidence of condensation at this building.

However, because of the construction deficiencies noted with the window installation, the incidence of condensation at this building will continue to be greater than if these concerns were addressed. Strategy 4 is the only approach that will appreciably reduce (but not eliminate) condensation accumulation and damage.

46


Previous Work by Others

→ Follow-up thermal modelling of window sill explored moving the window inwards



RDH

47




RDH

48

Existing Window System

- Allied Windows thermally broken aluminium frame window with “warm edge technology” insulating glass units
- Frames use thermal break to separate exterior from interior components
- Glass panes use thermally optimized spacer to improve thermal performance




RDH

49

Window System

- Shop drawings show thermal break at all mullions, including horizontal mullion previously reported to have a missing thermal break



RDH

50

RDH 2nd Opinion Review & Findings

- IGUs reviewed and tested for signs of failure
- Interior surfaces reviewed for damage due to wetting from both condensation and possible leakage
- Discussion with owners experiencing severe condensation



51

RDH Initial Review & Findings

- No failed IGUs found through visual review/testing
 - Glazing units are not systemically failing and do not need to be replaced
 - Some small percentage will fail and should be replaced under warranty
- Signs of severe condensation visible on glass surfaces
- Damage to interior window sills
- Condensation most severe in bedrooms
- Attempts to improve suite ventilation with fans unsuccessful
- Fairly standard window system and installation detail—though not ideal, it works on many other projects in BC



52

RDH Initial Review & Findings

- Severe condensation on interior surface of the thermally optimized IGUs, rather than just the window frame:
 - Is an indicator that interior moisture levels are a significant causal factor
 - Rules out glazing replacement as a valid repair solution
- Severe condensation on thermally broken aluminum mullions indicates that window replacement alone may not resolve the condensation issue in all suites
- Thermal modeling indicates negligible condensation resistance improvements by retrofitting the existing window installation



53

Recommendations

- Integrate mechanical, building enclosure, and occupant investigations together into one investigation that is developed to determine the exact cause of the problems
- Then perform and test mock-ups to confirm performance

→ Repair strategies should only be developed once causation has been determined

- Consultant 1 - recommendations:
 - ~~Strategy 1 - Occupant lifestyle change/review ventilation~~
 - ~~Strategy 2 - Retrofit existing operable windows due to (perceived) lack of thermal break. \$ 275K~~
 - ~~Strategy 3 - Replace IGUs with warm edge technology (WET) \$4.5M~~
 - ~~Strategy 4 - Replace all windows \$6.7M~~



54


RDH Full (Proper) Forensic Investigation – Steps 1 & 2

1. Owner Survey:

- Gather up-to-date information on the occurrences and severity of condensation

2. Ventilation System Operation & Window Leakage Testing:

- Air Testing of the mechanical system suite ventilation performance, including flow rate and condition of supply air to suites
- Water Testing of façade to rule out possibility of bulk water leakage causing increased ambient moisture levels and benchmark suite ventilation rates



55

RDH Full Investigation – Step 3

3. Advanced Monitoring:

- Installation of complete monitoring system in at least 4 suites (3 condensation and 1 control suite) in order to measure/monitor:
 - Window temperature and condensation occurrences
 - Ambient temperature/Relative Humidity/Carbon Dioxide
 - Ventilation/exhaust air flow at suite entry and bathrooms
 - Outdoor ambient conditions



56

Example Sensor Installations



RDH

57

Example Suite Sensor Layout Plan

- T/RH/Surface T
- T/RH/CO2
- T/RH/Fan Operation
- T/RH/Pressure - Corridor
- T/RH - Exterior



RDH

58

RDH Full Investigation – Steps 4 - 6

4. **Data Analysis:** Data from monitoring retrieved and analyzed to determine the main causal factors resulting in condensation
5. **Recommendations & Trial Repairs/Mock-up:** Formulate and implement a test repair strategy to minimize the condensation risk
6. **Follow Up Testing & Monitoring:** Continued shorter-term monitoring of suites with test repairs to determine effectiveness of the repair strategies

Repair strategies might include:

- Increasing the quality and quantity of ventilation air to suites to lower RH (HVAC or individual HRV)
- Improving heating of interior window surfaces
- In situ thermal improvements at window to wall interface
- Automation of exhaust fans



59


Outline

- Survey Results
- Ventilation Testing
- Initial Monitoring Data
- Ventilation Testing Results
- Trial Repairs
- Full Monitoring Data & Findings
- Window Review & Findings
- Energy Benchmarking
- Recommendations for Next Steps



60

Survey Results – Reported Severe Condensation




RDH

61

Ventilation Issues – Stack Effect

- Ventilation is hindered by improper HVAC balancing and stack effect forces
- Static HVAC balancing only works perfectly when not heavily influenced by stack effect.



RDH

62

Ventilation Mechanism – Pressurized Corridor

Corridor supply vent

Corridor

Air under door into suite

RDH

63

Ventilation Mechanism – Door Undercuts

→ Air can only enter suite with positive pressure and open path for airflow

No Gasket

Threshold Gasket

RDH

64

Ventilation System Testing

→ Ventilation and door airflow, exhaust fan airflow



RDH

65

Ventilation Testing Results

Corridor Ventilation Rates

Floor 5	Floor 7	Floor 9	Floor 16
~60 CFM	~60 CFM	~97 CFM	~127 CFM

Entry Door Pressure & Airflow – Single Point

502	702	902	Control
-5.5 Pascals (4.5 CFM)	-0.7 Pascals (14 CFM)	-0.8 Pascals (5.9 CFM)	6 Pascals
threshold gasket	no gasket	no gasket	47 CFM
			no gasket

(ASHRAE=30-50 cfm)

RDH

66

Sensor Installation

→ Four #02 suites

→ 3 test suites with condensation

→ 1 control suite with no condensation

T/RH/Surface T

T/RH/CO2

T/RH/Fan Operation

T/RH/Pressure/CO2

T/RH - Exterior

67

Sensor Installation

→ Ambient temperature, relative humidity, CO2

68

(C) RDH Building Science except as noted

34

Sensor Installation

→ Suite pressure, fan operation



69

Sensor Installation


→ Window surface temperatures



70


Sensor Locations

→ Window surface temperature sensor locations




71

Condensation Process



72


Remediation Option 1 – Reduce Dew Point Temp



RDH


73

Remediation Option 2 – Warm Surfaces




RDH


74




75




76




77



78



79



80

Remediation Option 1 – Reduce Dew Point Temp

OUTDOOR TEMPERATURE

INDOOR TEMPERATURE

INDOOR DEW POINT TEMPERATURE

OUTDOOR TEMPERATURE

INDOOR TEMPERATURE

INDOOR DEW POINT TEMPERATURE

RDH

81

Initial Monitoring Data

702 & 902 Surface Temperatures with 1602 Dew Point Temperatures

Temperature (°C)

Jan 08 Jan 13 Jan 18 Jan 23 Jan 28

— 702 MULLION TEMP — 902 MULLION TEMP — 1602 Mast Amb DP


902 CONDENSATION

702 CONDENSATION


Some condensation, but far less than before

RDH


82




83



84






85



86

Heating From Baseboard Heater - Limited







87

Initial Monitoring Data - Ventilation


Entry Door Airflow May Indicate Condensation Potential




CONTROL SUITE



88




89




90

Trial Repairs – Improved Ventilation Mechanism

Heat Recovery Ventilator




Approx. 40 CFM




91


Trial Repairs – Heat Recovery Ventilator



92



93



94

Monitoring - Findings


- Control suite received approximately recommended ventilation levels, had no signs of condensation, and maintained healthy CO2 levels
- Suites with no or minimal ventilation corresponded with condensation issues and had high CO2 levels, even with regular bathroom fan use
- Applying effects of ventilation to pre-HRV data shows far less condensation occurrences, though some condensation still may occur during cold periods
- All suites had similar ambient conditions, but highly varied window surface temperatures due to occupant behavior, heater use, window coverings



95


Window Review - Findings

- Windows are not great, but not the worst
- Window moisture leakage not reported to date
- Windows use thermally improved glass units, thermal breaks, and are installed in a standard arrangement at the sill
- Operable vents are not airtight and should receive adjustments and new gaskets



96

Window Review



RDH

97

Window Review – Adjustments & New Gaskets



RDH

98

HRV Retrofit Design: 2 Bed 2 Bath (16 Suites)

DUCT RUN - CEILING BULKHEAD



99

HRV Retrofit Design: 2 Bed 2 Bath Type A

DUCT RUN - CEILING BULKHEAD/BEAM



100

Forensic Investigation and Repair

- Install HRVs in all suites up to Floor 20 and add gasket to seal entry doors
- Modify existing ventilation system to prioritize corridors and suites on upper floors
- Service operable windows
- Take steps to further minimize condensation risk in suites
 - Maintain minimum heating levels to keep interior surfaces warm
 - Open blinds when not in use
 - Encourage ventilation/airflow within suite
- Cost: \$1.3-1.6 M

VS

Forensic Guessing and Repair

- Consultant 1 - Recommendations:
 - Strategy 1 - Occupant lifestyle change/review ventilation
 - Strategy 2 - Retrofit existing operable windows due to (perceived) lack of thermal break \$275K
 - Strategy 3 - Replace IGUs with warm edge technology (WET) \$4.5M
 - Strategy 4 - Replace all windows \$6.7M
- Don't be Dogbert !

101

FAILING FORWARD

Discussion + Questions

jstraube@rdh.com, brian@rdh.com


Learn more at rdh.com

RDH Building Science
 @RDHBuildings

102

102


Learn More



RDH Technical Library

Building enclosure articles, conference papers, presentations, research reports, quick guides + technical bulletins

rdh.com/technical-library



Learn Building Science

Live events, guides, courses + more!

learnbuildingscience.com

